

- Fix up ACPI problem to enable power for IR220L+, IR220 and IR200.
- Supports Windows 98/2000/Me/XP operating system.



GO WIRELESS WITH ACTISYS IR
ACTiLinkACPI

for IR220L+, IR220, IR200 IrDA-SIR Adapter

Tel: (510) 490-8024, Fax: (510) 623-7268
E-mail: irda-support@actisys.com
Web: <http://www.actisys.com/>

48511 Warm Springs Blvd, Suite 206 Fremont, CA 94539, USA
(C) Copyright 2000-2001 ACTISYS Corporation, All Rights Reserved

The image shows a black, rectangular IrDA-SIR adapter with a red light on the front. It is connected to a black cable that ends in a standard PC IrDA port connector. The adapter has a yellow circular logo with a stylized 'E' and the text 'ACTISYS IR' and 'IrDA-SIR Adapter' on its top surface.